ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

1.General Details

Zone No:Dasarahalli **Ward No:14** **Ward Name:Bagalakunte**

Street ID: W0357,W0402,W0355,W0398,W0358,W0356,W0357,W0398 **Street Name: 1st Crs**

Significant Landmark: MEI Layout

Segment_No: 14/S-W0398/S12771 **Total_Length: 228.19**

Segment Details

Seg No.	Length(mts)	Start Coordinates	End Coordinates	From Landmark	To Landmark	Work Type	Other Work
1	110.83	13.058584232951103-77.50263065099718	13.059522242837978-77.5029766559601	MEI Layout 10 th cross	Police station road	Others	CC drain
2	89.42	13.059938989820344-77.5012855231762	13.059852766364436-77.50210627913475	Bagalagunte police station	2nd cross	Others	C C Drain
3	27.94	13.058679601806995-77.5026933476329	13.058613300859712-77.50294212251903	Police Station road	1st cross	Others	CC drain

2.Work Details

History of Road / Lane / Circles

Name of the Work:Desilting and resetting of drain to MEI Layout new Extension main roads and cross roads in ward No 14 Bagalagunte

Sanctioned Amount: 3920000 **Sanctioned Year: 2021-22** **Year: 2021-22**

Tender: Tender **Work Details: WO 356 and WO 357 Both side of drain** **Job No/Work Code:014-18-000076**

Work Order No: EE/DD/WO/79/21-22 Work Order Date: 05/07/2022 Period of Extention: 0

Defect Liability Period From: 29/09/2023 Defect Liability Period To: 28/09/2024

3.Contractor Details

Zone: Dasarahalli Ward No: 14 Ward Name: Bagalakunte

Street ID: W0398 Name of Contractor: AswathappaG Contractor Reg No (BBMP/PWD): CBSC1CIVIL118862020

4.Field Inspection Details

Category	Image		
Desilting and resetting of drain to MEI Layout new Extension main roads and cross roads in ward No 14 Bagalagunte			

Remarks

Sl.No	Stage_No	Designation	Remarks	StageName	Action
1	1	AE	Road Work History Added	Data Uploading	Initated
2	2	AEE	-	Review Application	Initated